

A/C Type: **Robinson R44 II**
A/C Reg: **LN-OKB**
A/C S/N: **12381**

Date: **23.05.2025**
A/C Tach: **2626,0**
A/C Landings: **UNK**

TSO: **1952,1**

Aircraft Status List

Component				Installed/Last C/W		Component		Maintenance			
ATA	Part Name	Part No.	Serie No.	Date	A/C T:T:	TSN	TSO	Interval	Work / Inspection	Next Due	Remaining
04-10-00	Robinson R44 II	R44 II	12381	30.10.24	2 560,5			1 Y	ARC - 2nd Extension	30.10.25	160 D
05-20-01	Robinson R44 II	R44 II	12381	31.07.24	2 556,3			100 H	100 Hrs Inspection	2 656	30 H
05-20-01	Robinson R44 II	R44 II	12381	31.07.24	2 556,3			1 Y	100 Hrs Inspection	31.07.25	69 D
05-20-02	Robinson R44 II	R44 II	12381	23.07.20	673,9			2 200 H	A/C Time Due OH	2 874	248 H
05-20-03	Robinson R44 II	R44 II	12381	23.07.20	673,9			12 Y	A/C Time Due OH	23.07.32	2 618 D
05-30-01	Robinson R44 II	R44 II	12381	31.10.24	2 560,5			2 Y	Compass Swing	31.10.26	526 D
05-30-02	Robinson R44 II	R44 II	12381	31.10.24	2 560,5			2 Y	Pitot/Static Ramp Check	31.10.26	526 D
05-30-03	Robinson R44 II	R44 II	12381	31.10.24	2 560,5			2 Y	EASA SIB 2011-15 R2: Mode C Chk	31.10.26	526 D
05-50-01	Robinson R44 II	R44 II	12381	07.01.25				300 H	EASA AD 2024-23-01 within 7/1/26	2 860	234 H
25-19-01	Dart Cabin Floor Protectors	D044-719-011	B37240	10.09.08	4,3				Installed		
25-19-01	Dart Cabin Floor Protectors	D044-719-011	B37240	12.09.23	2 378,1			300 H	300 Hrs Insp. as per ICA-D044-719	2 680	54 H
25-27-01	Portable Fire Extinguisher	B381-1	D58288705	13.06.19	458,9			12 Y	Fire Extinguisher, Life Limit	31.12.29	1 683 D
25-27-01	Portable Fire Extinguisher	B381-1	D58288705	31.07.24	2 556,3			1 Y	Fire Extinguisher, Weight Check	31.07.25	69 D
25-27-01	Portable Fire Extinguisher	B381-1	D58288705	15.06.23	2 178,1			1 M	Fire Extinguisher, Control (Pre Flight)		
25-29-01	Kannad 406 AF-H ELT	S1821502-02	2611711-0119	03.07.08	0,0	2 626,0			Installed		
25-29-01	Kannad 406 AF-H ELT	S1821502-02	2611711-0119	31.10.24	2 560,5			1 Y	Periodic Inspection, SL S18XX502-25-12	31.10.25	161 D
25-29-01-01	ELT Battery (BAT300)	S1820506-01	22 060 325	21.06.22	1 580,2			6 Y	ELT Battery, Life (01/2029)	31.01.29	1 349 D
25-85-01	Tanis Preheater System	TAS100	416628	10.09.09	4,3				Installed		
25-85-01	Tanis Preheater System	TAS100	416628	31.07.24	2 556,3			1 Y	Tanis ICA TCA1000, § 2.4, Rev. D	31.07.25	69 D
28-33-01	Pressure Relief Valve	D321-1	N/A	23.07.20	673,9			2 200 H	Pressure Relief Valve, Replacement	2 874	248 H
28-33-01	Pressure Relief Valve	D321-1	N/A	23.07.20	673,9			12 Y	Pressure Relief Valve, Replacement	23.07.32	2 618 D
28-33-01	Pressure Relief Valve	D321-1	N/A	31.07.24	2 556,3			1 Y	Check as per MM 12-83	31.07.25	69 D
29-01-01	Hydraulic Actuator Assy	D212-1	8094	23.07.20	673,9	UNK	1 952,1	2 200 H	Hydraulic Actuator Assy, Time Due OH	2 874	248 H
29-01-02	Hydraulic Actuator Assy	D212-1	9518	23.07.20	673,9	UNK	1 952,1	2 200 H	Hydraulic Actuator Assy, Time Due OH	2 874	248 H
29-01-03	Hydraulic Actuator Assy	D212-1	11013	23.07.20	673,9	UNK	1 952,1	2 200 H	Hydraulic Actuator Assy, Time Due OH	2 874	248 H
29-07-01	Hydraulic Reservoir	D211-2	2514	23.07.20	673,9	UNK	1 952,1	2 200 H	Hydraulic Reservoir, Time Due OH	2 874	248 H
29-07-02	Hydraulic Filter	AN6235-1A	N/A	24.04.24	2 474,6			300 H	Hyd. Filter, Replacement	2 780	154 H
29-17-01	Hydraulic Pump	D500-1	3430	23.07.20	673,9	UNK	1 952,1	2 200 H	Hydraulic Pump, Time Due OH	2 874	248 H
53-19-01	Upper Frame Assy	C020-1	10306	23.07.20	673,9	1 952,1		2 200 H	Upper Frame Assy, Life Limit	2 874	248 H
53-25-01	Tailcone Assy.	C023-1	4932	03.07.08	0,0	2 626,0		4 400 H	Tailcone Assy, Life Limit	4 400	1 774 H
53-37-01	Horizontal Stabilizer	C044-1	9855	13.06.19	458,9	2 167,1		4 400 H	Horizontal Stabilizer, Life Limit	4 859	2 233 H
53-37-02	Tail Rotor Guard	D079-1	12156	23.07.20	673,9	1 952,1		2 200 H	TR Guard, Life Limit	2 874	248 H
62-01-01	Main Rotor Blade No 1	C016-7	12198	23.07.20	673,9	1 952,1		2 200 H	MRB, Life Limit	2 874	248 H
62-01-01	Main Rotor Blade No 1	C016-7	12198	23.07.20	673,9			12 Y	MRB, Life Limit	24.02.32	2 468 D
62-01-01-01	Main Rotor Spindel No 1	C158-1	25949	23.07.20	673,9	1 952,1		2 200 H	MR Spindel, Life Limit	2 874	248 H
62-01-02	Main Rotor Blade No 2	C016-7	12206	23.07.20	673,9	1 952,1		2 200 H	MRB, Life Limit	2 874	248 H

A/C Type: **Robinson R44 II**
A/C Reg: **LN-OKB**
A/C S/N: **12381**

Date: **23.05.2025**
A/C Tach: **2626,0**
A/C Landings: **UNK**

TSO: **1952,1**

Aircraft Status List

Component				Installed/Last C/W		Component		Maintenance			
ATA	Part Name	Part No.	Serie No.	Date	A/C T:T	TSN	TSO	Interval	Work / Inspection	Next Due	Remaining
62-01-02	Main Rotor Blade No 2	C016-7	12206	23.07.20	673,9			12 Y	MRB, Life Limit	24.02.32	2 468 D
62-01-02-01	Main Rotor Spindel No 2	C158-1	25950	23.07.20	673,9	1 952,1		2 200 H	MR Spindel, Life Limit	2 874	248 H
62-07-01	Main Rotor Hub	C154-1	11529	23.07.20	673,9	1 952,1		2 200 H	Main Rotor Hub, Life Limit	2 874	248 H
63-01-01	MR Gearbox	C006-7	5390	23.07.20	673,9	UNK	1 952,1	2 200 H	MRGB, Time Due OH	2 874	248 H
63-01-01	MR Gearbox	C006-7	5390	15.06.23	2 178,1			500 H	MRGB, Oil Change (MM 1.120)	2 680	54 H
63-01-01	MR Gearbox	C006-7	5390	31.07.24	2 556,3			1 Y	Clean Chip Detector (MM 1.115)	31.07.25	69 D
63-01-01-01	Main Rotor Shaft	C251-2	R2610	23.07.20	673,9	1 952,1		2 200 H	Main Rotor Shaft, Time Due OH	2 874	248 H
63-01-01-02	MRGB Housing	C264-2	10780	23.07.20	673,9	1 952,1		2 200 H	MRGB Housing, Life Limit	2 874	248 H
63-01-01-03	MRGB Sump	C263-2	8320	23.07.20	673,9	1 952,1		2 200 H	MRGB Sump, Life Limit	2 874	248 H
63-01-01-04	Main Rotor Gearset	C146-2	11158	23.07.20	673,9	1 952,1		2 200 H	MR Gearset, Life Limit	2 874	248 H
63-13-10	Yoke	C907-1	N/A	23.07.20	673,9	1 952,1			Installed (TSN: 0,0)		
63-15-01-01	Sprag Clutch	C188-3	12856	23.07.20	673,9	1 952,1		2 200 H	Sprag Clutch, Time Due OH	2 874	248 H
63-15-01-01	Sprag Clutch	C188-3	12856	15.06.23	2 178,1			500 H	Sprag Clutch, Service MM 7.210	2 680	54 H
63-15-01-02	Clutch Shaft	C166-5	1834	23.07.20	673,9	1 952,1		2 200 H	Clutch Shaft, Time Due OH	2 874	248 H
63-19-01	Actuator Assy.	C051-2	4824	23.07.20	673,9	UNK	1 952,1	2 200 H	Actuator, Time Due OH	2 874	248 H
63-19-02	Shaft and Bearing Assy	C007-5	N/A	25.02.22	1 305,5	1 320,5		2 200 H	Shaft & Bearing Assy, Time Due OH	3 506	880 H
63-19-02-01	Bearing Assy./Lower Sheave	C181-3	11701	24.04.24	2 474,6			300 H	C181-3 Bearing Lubrication (MM 1.140)	2 780	154 H
63-19-02-01	Bearing Assy./Lower Sheave	C181-3	11701	24.04.24	2 474,6			3 Y	C181-3 Bearing Lubrication (MM 1.140)	24.04.27	701 D
64-01-01	Tail Rotor Blade No 1	C029-3	14621	24.11.22	1 871,9	754,1		2 200 H	TRB, Life Limit	4 072	1 446 H
64-01-01	Tail Rotor Blade No 1	C029-3	14621	24.11.22	1 871,9			12 Y	TRB, Life Limit	12.10.34	3 429 D
64-01-01	Tail Rotor Blade No 2	C029-3	14627	24.11.22	1 871,9	754,1		2 200 H	TRB, Life Limit	4 072	1 446 H
64-01-01	Tail Rotor Blade No 2	C029-3	14627	24.11.22	1 871,9			12 Y	TRB, Life Limit	12.10.34	3 429 D
64-01-02	Tail Rotor Hub Assy	G062-2	6267	23.07.20	673,9	1 952,1		2 200 H	TR Hub Assy, Life Limit	2 874	248 H
64-05-03	Tail Rotor Pitch Control Assy	C031-1	12182	23.07.20	673,9	1 952,1		2 200 H	TR Pitch Control Assy, Time Due OH	2 874	248 H
65-01-01	Tail Rotor Drive Shaft	D196-1	9566	23.07.20	673,9	1 952,1		4 400 H	TRDS, Life Limit	5 074	2 448 H
65-07-01	Tail Rotor Gearbox	C021-1	4673	23.07.20	673,9	UNK	1 952,1	2 200 H	TRGB, Time Due OH	2 874	248 H
65-07-01	Tail Rotor Gearbox	C021-1	4673	15.06.23	2 178,1			500 H	TRGB, Oil Change (MM 1.130)	2 680	54 H
65-07-01	Tail Rotor Gearbox	C021-1	4673	31.07.24	2 556,3			1 Y	Clean Chip Detector (MM 1.115)	31.07.25	69 D
65-07-01-01	Tail Rotor Gearset	C545-2	12192	23.07.20	673,9	1 952,1		2 200 H	TR Gearset, Life Limit	2 874	248 H
67-61-01	Main Rotor Swashplate	C017-6	5246	23.07.20	673,9	1 952,1		2 200 H	Main Rotor Swashplate, Time Due OH	2 874	248 H
67-61-01-01	Bearing Set	C647-12	C192611	23.07.20	673,9	1 952,1		2 200 H	Swashplate Bearing Set, Life Limit	2 874	248 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	25.08.20	676,5	2 626,0	1 952,1	2 200 H	Engine, Time Due OH	2 874	248 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	25.08.20	676,5			12 Y	Engine, Time Due OH	12.03.32	2 485 D
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	14.03.25	2 603,4			50 H	50 Hrs Engine Inspection	2 653	27 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	14.03.25	2 603,4			50 H	Lyc. SI 1080C	2 653	
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	31.07.24	2 556,3			100 H	Lyc. SI 1129D (Inc. 100H)	2 656	

A/C Type: **Robinson R44 II**
A/C Reg: **LN-OKB**
A/C S/N: **12381**

Date: **23.05.2025**
A/C Tach: **2626,0**
A/C Landings: **UNK**

TSO: **1952,1**

Aircraft Status List

Component				Installed/Last C/W		Component		Maintenance		Next Due	Remaining
ATA	Part Name	Part No.	Serie No.	Date	A/C T:T	TSN	TSO	Interval	Work / Inspection		
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	31.07.24	2 556,3			100 H	Lyc. SI 1191A: Comp. Chk.	2 656	30 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	24.04.24	2 474,6			300 H	Lyc. SB 301B, Item #1: Valve Insp.	2 780	154 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	31.07.24	2 556,3			100 H	Lyc. SB 342G	2 656	30 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	31.07.24	2 556,3			1 Y	Lyc. SB 342G	31.07.25	69 D
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	24.04.24	2 474,6			300 H	Lyc. SB 388C: Valve Steam Clearance	2 780	154 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	14.03.25	2 603,4			50 H	Lyc. SB 480F: Engine Oil Change	2 653	27 H
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	14.03.25	2 603,4			4 M	Lyc. SB 480F: Engine Oil Change	01.07.25	40 D
71-09-01	Engine	IO-540-AE1A5	L-32955-48E	14.03.25	2 603,4			50 H	Lyc. SB 650	2 653	27 H
71-51-01	Alternator	ALU-8521-9	H-S123518	03.09.21	1 124,9	UNK	1 501,1	2 200 H	Alternator, Time due OH	3 325	699 H
71-51-01	Alternator	ALU-8521-9	H-S123518	03.09.21	1 124,9			12 Y	Alternator, Time due OH	03.09.33	3 025 D
71-51-02	Starter	BC315-100-4	2A11D1Q42	03.09.21	1 124,9	UNK	1 501,1	2 200 H	Starter, Time due OH	3 325	699 H
71-51-02	Starter	BC315-100-4	2A11D1Q42	03.09.21	1 124,9			12 Y	Starter, Time due OH	03.09.33	3 025 D
74-01-01	Ignition System	N/A	N/A	31.07.24	2 556,3			100 H	CMI SB636 & SB653 (Inc.100H)	2 656	
74-01-02	Magnetos (LH/RH)	N/A	N/A	31.07.24	2 556,3			100 H	CMI SB643C, Item II.A. (Inc. 100H)	2 656	
74-05-01	L/H Magneto (S6LSC-200)	10-600616-9	J-01011	16.08.21	1 078,1	UNK	1 547,9	2 200 H	CMI SB643C, Item II.D. Repl. Magneto	3 278	652 H
74-05-01	L/H Magneto (S6LSC-200)	10-600616-9	J-01011	16.08.21	1 078,1			4 Y	CMI SB643C, Item II.D. Repl. Magneto	16.08.25	85 D
74-05-01	L/H Magneto (S6LSC-200)	10-600616-9	J-01011	02.08.23	2 274,0			500 H	CMI SB643C, Item II.C: 500H Insp.	2 780	154 H
74-05-01	L/H Magneto (S6LSC-200)	10-600616-9	J-01011	02.08.23	2 274,0			500 H	Verify magneto drive cushion pliability	2 780	154 H
74-05-02	R/H Magneto (S6LSC-204T)	10-600646-201	E12FA014	24.04.24	2 474,6	UNK	151,4	2 200 H	CMI SB643C, Item II.D. Repl. Magneto	4 675	2 049 H
74-05-02	R/H Magneto (S6LSC-204T)	10-600646-201	E12FA014	24.04.24	2 474,6			4 Y	CMI SB643C, Item II.D. Repl. Magneto	24.04.28	1 067 D
74-05-02	R/H Magneto (S6LSC-204T)	10-600646-201	E12FA014	24.04.24	2 474,6			500 H	CMI SB643C, Item II.C: 500H Insp.	2 980	354 H
74-05-02	R/H Magneto (S6LSC-204T)	10-600646-201	E12FA014	24.04.24	2 474,6			500 H	Verify magneto drive cushion pliability	2 980	354 H
74-10-01	Ignition Harness, LH	M2463	N/A	23.07.20	673,9			2 200 H	CMI SB643C, Item II.D.1.b. - Replace	2 874	248 H
74-10-01	Ignition Harness, LH	M2463	N/A	23.07.20	673,9			12 Y	CMI SB643C, Item II.D.1.b. - Replace	23.07.32	2 618 D
74-10-02	Ignition Harness, RH	M2464	N/A	23.07.20	673,9			2 200 H	CMI SB643C, Item II.D.1.b. - Replace	2 874	248 H
74-10-02	Ignition Harness, RH	M2464	N/A	23.07.20	673,9			12 Y	CMI SB643C, Item II.D.1.b. - Replace	23.07.32	2 618 D
76-17-01	Fuel Control Servo (RSA-10AD1)	2576630-4	7206YU05	16.08.21	1 078,1	UNK	1 988,4	2 200 H	Fuel Control, Time due OH	2 838	212 H
76-17-01	Fuel Control Servo (RSA-10AD1)	2576630-4	7206YU05	16.08.21	1 078,1			12 Y	Fuel Control, Time due OH	23.07.32	2 618 D
79-01-01	Oil Cooler	10886A	4308	23.07.20	673,9	2 626,0	1 952,1	2 200 H	Oil Cooler, Inspection/Test	2 874	248 H
79-01-01	Oil Cooler	10886A	4308	23.07.20	673,9			12 Y	Oil Cooler, Inspection/Test	23.07.32	2 618 D
79-03-01	Oil Cooler (Small)	10942A	905	23.07.20	673,9	2 626,0	1 952,1	2 200 H	Oil Cooler, Inspection/Test	2 874	248 H
79-03-01	Oil Cooler (Small)	10942A	905	23.07.20	673,9			12 Y	Oil Cooler, Inspection/Test	23.07.32	2 618 D
95-21-01	Engine/Rotor Tachometer	C792-4	7865	23.07.20	673,9	1 952,1		2 200 H	Tachometer, Time Due OH	2 874	248 H
95-21-01	Engine/Rotor Tachometer	C792-4	7865	23.07.20	673,9			12 Y	Tachometer, Time Due OH	23.07.32	2 618 D
96-63-01	Controller Governor	D278-2	4991	23.07.20	673,9	1 952,1		2 200 H	Controller Governor, Time Due OH	2 874	248 H
96-63-01	Controller Governor	D278-2	4991	23.07.20	673,9			12 Y	Controller Governor, Time Due OH	23.07.32	2 618 D

A/C Type: Robinson R44 II

Date: 23.05.2025

Aircraft Status List

A/C Reg: LN-OKB

A/C Tach: 2626,0

TSO: 1952,1

A/C S/N: 12381

A/C Landings: UNK

Component		Installed/Last C/W			Component		Maintenance				
ATA	Part Name	Part No.	Serie No.	Date	A/C T:T:	TSN	TSO	Interval	Work / Inspection	Next Due	Remaining